

Summary

FROM: 26-04-30 08:00 TO: 26-04-30 09:30 OBBB A0337/25
OBBI - BAHRAIN INTERNATIONAL
D) BTN 0800-0930
E) TWY A AND Z CLOSED, INCLUDING TAXI LANE K, L AND BACK OF CARGO
APRON
STANDS

FROM: 26-10-09 00:50 TO: 26-10-24 03:15 OBBB A0334/25
OBBI - BAHRAIN INTERNATIONAL
D) DLY BTN 0050-0315
E) RWY 30R/12L CLOSED DUE TO WIP

FROM: 26-09-10 08:00 TO: 26-09-10 09:30 OBBB A0333/25
OBBI - BAHRAIN INTERNATIONAL
D) BTN 0800-0930
E) RWY 30R/12L CLOSED DUE TO WALKING INSPECTION

FROM: 26-06-05 00:50 TO: 26-06-20 03:15 OBBB A0332/25
OBBI - BAHRAIN INTERNATIONAL
D) DLY BTN 0050-0315
E) RWY 30R/12L CLOSED DUE TO WIP

FROM: 26-04-30 08:00 TO: 26-04-30 09:30 OBBB A0331/25
OBBI - BAHRAIN INTERNATIONAL
D) BTN 0800-0930
E) RWY 30R/12L CLOSED DUE TO WALKING INSPECTION

CNS OBBB A0025/26
FROM: 26-01-28 05:30 TO: 26-04-28 23:59
QBBS - BAHRAIN / ISA AIRBASE
D) H24
E) ISA AIR BASE TACAN CH 123X U/S

INFO OBBB A0065/26 REPLACED BY OBBB A0135/26
FROM: 26-04-01 11:36 TO: 26-05-01 23:59 EST
QBBB - BAHRAIN
E) CHECKLIST
SERIES A
2025:0331 0332 0333 0334 0337 0338 0339 0340 0374 0383 0394 0395 0396
0401 0402 0408
2026:0002 0003 0019 0022 0023 0025 0032 0033 0052 0053 0054 0055 0056
0108 0134
LATEST PUBLICATIONS
AIP AIRAC AMDT 01/26 EFF DATE 19 MAR 2026 PUBLICATION DATE 19 FEB
2026
SUP CHECKLIST 11/19, 02/22, 03/22, 05/22, 03/23, 04/25 AND 05/25
AIC CHECKLIST 02/24 AND 01/26)

FROM: 26-01-31 06:35 TO: 26-04-30 23:59 EST OBBB A0345/25 REPLACED BY OBBB A0033/26
OBBI - BAHRAIN INTERNATIONAL
D) H24

Summary

E) POTENTIAL GPS SIGNAL INTERFERENCE WITHIN THE VICINITY OF THE
AERODROME ARR/DEP ARE REQUIRED TO NOTIFY THE RELEVANT ATS UNIT IF GPS
SIGNAL INTERFERENCE OCCURS IN THE AREA

OBBB A0344/25 REPLACED BY OBBB A0032/26

FROM: 26-01-31 06:34 TO: 26-04-30 23:59 EST

OBBB - BAHRAIN

D) H24

E) POTENTIAL GPS SIGNAL INTERFERENCE WITHIN BAHRAIN FIR.
PILOTS ARE REQUIRED TO NOTIFY THE RELEVANT ATS UNIT IF GPS SIGNAL
LOSS OCCURS IN THE AREA.

OBBB A0342/25 REPLACED BY OBBB A0023/26

FROM: 26-01-27 05:33 TO: 26-04-27 23:59 EST

OBBI - BAHRAIN INTERNATIONAL

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 66M, POSITIONS AT APPROX
DIST 2.8KM MAG BRG 193 DEG FROM RWY 12L THR.

OBBB A0341/25 REPLACED BY OBBB A0022/26

FROM: 26-01-27 05:32 TO: 26-04-27 23:59 EST

OBBI - BAHRAIN INTERNATIONAL

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 225M, POSITIONS AT APPROX
DIST 3.3NM MAG BRG 231 DEG FROM RWY 12L THR.

OBBB A0327/25 REPLACED BY OBBB A0019/26

FROM: 26-01-25 11:27 TO: 26-04-25 23:59 EST

OBBS - BAHRAIN / ISA AIRBASE

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 60M, POSITIONS AT APPROX DIST
960M MAG BRG 257 DEG FROM RWY 15R THR

OBBB A0311/25 REPLACED BY OBBB A0003/26

FROM: 26-01-06 05:29 TO: 26-03-06 23:59 EST

OBBI - BAHRAIN INTERNATIONAL

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 60M, POSITIONS AT APPROX DIST
2.94KM MAG BRG 227 DEG FROM RWY 12L THR.

OBBB A0310/25 REPLACED BY OBBB A0002/26

FROM: 26-01-06 05:07 TO: 26-03-06 23:59 EST

OBBI - BAHRAIN INTERNATIONAL

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 60M, POSITIONS AT APPROX DIST
3.06KM MAG BRG 228 DEG FROM RWY 12L THR.

OBBB A0299/25 REPLACED BY OBBB A0408/25

FROM: 25-12-17 12:11 TO: 26-03-17 23:59 EST

OBKH - BAHRAIN / SAKHIR AIRBASE

D) DLY BTN 0600-2200

E) OBST CRANE WILL BE ERECTED AT HEIGHT 40M, POSITIONED AT APRX DIST
2KM MAG BRG 234 DEG FRM RWY 35 THR.

OBBB A0281/25 REPLACED BY OBBB A0396/25

FROM: 25-12-04 07:01 TO: 26-03-04 23:59 EST

OBBB - BAHRAIN

Summary

E)
OPERATORS INTENDING TO OPERATE BOEING 737-8 (MAX) AND 737-9 (MAX)
FROM OR TO THE KINGDOM OF BAHRAIN OR INTENDING TO OVERFLY BAHRAIN
AIRSPACE, SHALL COMPLY WITH THE REQUIREMENTS STIPULATED IN BAHRAIN
CAA CIRCULAR NO.AC/ALD-OPS/01/2021 DATED 2 MARCH 2021.

OBBB A0280/25 REPLACED BY OBBB A0395/25

FROM: 25-12-04 07:00 TO: 26-03-04 23:59 EST

OBBB - BAHRAIN

E)

TRAFFIC ENTERING BAHRAIN FIR AT POSITION RABAP AND LONOS BE AWARE
THAT THIS IS AN AREA OF HIGH CONCENTRATION OF MILITARY ACTIVITY AND
CIVILIAN CROSSING TRAFFIC. PILOTS SHALL STRICTLY KEEP LISTENING
WATCH TO THE APPROPRIATE ATC FREQUENCIES AND SHALL ADHERE STRICTLY
TO ATC INSTRUCTIONS.

ATM

OBBB A0362/25 REPLACED BY OBBB A0052/26

FROM: 26-02-11 12:44 TO: 26-05-11 23:59 EST

OBBB - BAHRAIN

E) POSITION KUVAR IS NOT AVAILABLE FOR ENTRY INTO THE OBBB FIR.

OBBB A0279/25 REPLACED BY OBBB A0394/25

FROM: 25-12-04 06:59 TO: 26-03-04 23:59 EST

OBBB - BAHRAIN

E)

REMINDER, REFERENCE BAHRAIN EAIP, ENR 3.3
AREA NAVIGATION (RNAV) ROUTES. ALL TRAFFIC VIA:
L602, T602, M600 TO BE IN LEVEL FLIGHT BEFORE ALTOM
L768 TO BE IN LEVEL FLIGHT BEFORE RAMKI
T557 TO BE IN LEVEL FLIGHT BEFORE VELAK
IF UNABLE ADVISE BAHRAIN ATC ON INITIAL CONTACT

OBBB A0383/25

FROM: 25-11-30 06:08 TO: 26-02-28 23:59 EST

OBBB - BAHRAIN

E) ALL OPERATORS OF AIRBUS A319/A320/A321 AIRPLANES INTENDING FLYING
INTO/FROM OR OVERFLYING BAHRAIN FIR MUST COMPLY WITH EASA EMERGENCY
AIRWORTHINESS DIRECTIVE 2025-0268-E ISSUED 28 NOV 2025. OPERATORS
MUST ENSURE FULL COMPLIANCE PRIOR TO ENTRY INTO BAHRAIN FIR. FOR MORE
INFO CONTACT AIRWORTHINESS DEPARTMENT, AEROLICENSING (A) MTT.GOV.BH

WARN

OBBB A0376/25 REPLACED BY OBBB A0056/26

FROM: 26-02-25 11:18 TO: 26-05-25 23:59 EST

OBBB - BAHRAIN

D) DAILY BTN 0630-0845

E) GUN FIRING WILL TAKE PLACE WITH THE FLW COORDINATES:

275000N 0493600E

272600N 0495100E

272700N 0502700E

273700N 0502200E

275100N 0495200E

THE ABOVE RECEIVED FROM JEDDAH

F) SFC

G) 5000FT AMSL

OBBB A0375/25 REPLACED BY OBBB A0055/26

FROM: 26-02-25 11:15 TO: 26-05-25 23:59 EST

OBBB - BAHRAIN

Summary

D) DLY BTN 0900-1100

E) MIL EXERCISE WILL TAKE PLACE WI THE FLW COORDS:

270000N 0502500E

281700N 0491000E

282300N 0492400E

272500N 0503300E

THE ABOVE RECEIVED FROM JEDDAH.

F) 5000FT AMSL

G) 10000FT AMSL

OBBB A0325/25 REPLACED BY OBBB A0374/25

FROM: 25-11-25 12:44 TO: 26-02-26 23:59 EST

OBBB - BAHRAIN

D) DAILY BTN 0630-0845

E) OED46 DANGER AREA ACTIVATED

THE ABOVE RECEIVED FROM JEDDAH.

F) SFC

G) 4000FT AMSL

---END OF DOCUMENT---