

Summary

E) TWY A AND Z CLOSED, INCLUDING TAXI LANE K, L AND BACK OF CARGO
APRON
STANDS

OBBB A0334/25

FROM: 26-10-09 00:50 TO: 26-10-24 03:15
OBBI - BAHRAIN INTERNATIONAL
D) DLY BTN 0050-0315
E) RWY 30R/12L CLOSED DUE TO WIP

OBBB A0333/25

FROM: 26-09-10 08:00 TO: 26-09-10 09:30
OBBI - BAHRAIN INTERNATIONAL
D) BTN 0800-0930
E) RWY 30R/12L CLOSED DUE TO WALKING INSPECTION

INFO

OBBB A0200/26 REPLACED BY OBBB A0227/26

FROM: 26-07-01 00:01 TO: 26-10-01 23:59 EST
OBBB - BAHRAIN / ISA AIRBASE
D) H24
E) OBST CRANE WILL BE ERECTED AT HEIGHT 60M, POSITIONS AT APPROX DIST
960M MAG BRG 257 DEG FROM RWY 15R THR

OBBB A0224/26

FROM: 26-07-01 01:00 TO: 26-09-30 15:30
OBBI - BAHRAIN INTERNATIONAL
D) DLY BTN 0100-1530
E) OBST CRANE AT HEIGHT 50M MOVING BETWEEN POSITIONS APPROX DIST
527M,
MAG BRG 92 DEG AND DIST 606M, MAG BRG 67 DEG FROM RWY 30R THR.

OBBB A0395/25 REPLACED BY OBBB A0198/26

FROM: 26-06-03 10:56 TO: 26-09-03 23:59 EST
OBBB - BAHRAIN
E)
TRAFFIC ENTERING BAHRAIN FIR AT POSITION RABAP AND LONOS BE AWARE
THAT THIS IS AN AREA OF HIGH CONCENTRATION OF MILITARY ACTIVITY AND
CIVILIAN CROSSING TRAFFIC. PILOTS SHALL STRICTLY KEEP LISTENING
WATCH TO THE APPROPRIATE ATC FREQUENCIES AND SHALL ADHERE STRICTLY
TO ATC INSTRUCTIONS.

OBBB A0190/26

FROM: 26-05-23 16:33 TO: 26-07-31 23:59 EST
OBBB - BAHRAIN
E) POTENTIAL GPS SIGNAL INTERFERENCE WITHIN BAHRAIN FIR AND AT OBBI
DURING START-UP, TAXI AND TAKEOFF. PILOTS ARE REQUIRED TO NOTIFY THE
RELEVANT ATS UNIT IF GPS SIGNAL LOSS OR INTERFERENCE OCCURS.

OBBB A0342/25 REPLACED BY OBBB A0023/26

FROM: 26-01-27 05:33 TO: 26-04-27 23:59 EST
OBBI - BAHRAIN INTERNATIONAL
D) H24
E) OBST CRANE WILL BE ERECTED AT HEIGHT 66M, POSITIONS AT APPROX
DIST 2.8KM MAG BRG 193 DEG FROM RWY 12L THR.

OBBB A0341/25 REPLACED BY OBBB A0022/26

FROM: 26-01-27 05:32 TO: 26-04-27 23:59 EST
OBBI - BAHRAIN INTERNATIONAL
D) H24

Summary

E) OBST CRANE WILL BE ERECTED AT HEIGHT 225M, POSITIONS AT APPROX
DIST 3.3NM MAG BRG 231 DEG FROM RWY 12L THR.

OBBB A0311/25 REPLACED BY OBBB A0003/26

FROM: 26-01-06 05:29 TO: 26-03-06 23:59 EST

OBBI - BAHRAIN INTERNATIONAL

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 60M, POSITIONS AT APPROX DIST
2.94KM MAG BRG 227 DEG FROM RWY 12L THR.

OBBB A0310/25 REPLACED BY OBBB A0002/26

FROM: 26-01-06 05:07 TO: 26-03-06 23:59 EST

OBBI - BAHRAIN INTERNATIONAL

D) H24

E) OBST CRANE WILL BE ERECTED AT HEIGHT 60M, POSITIONS AT APPROX DIST
3.06KM MAG BRG 228 DEG FROM RWY 12L THR.

OBBB A0299/25 REPLACED BY OBBB A0408/25

FROM: 25-12-17 12:11 TO: 26-03-17 23:59 EST

QBKH - BAHRAIN / SAKHIR AIRBASE

D) DLY BTN 0600-2200

E) OBST CRANE WILL BE ERECTED AT HEIGHT 40M, POSITIONED AT APRX DIST
2KM MAG BRG 234 DEG FRM RWY 35 THR.

ATM

OBBB A0052/26 REPLACED BY OBBB A0183/26

FROM: 26-05-12 10:44 TO: 26-08-12 23:59 EST

OBBB - BAHRAIN

E) POSITION KUVAR IS NOT AVAILABLE FOR ENTRY INTO THE OBBB FIR.

OBBB A0383/25 REPLACED BY OBBB A0165/26

FROM: 26-04-29 10:07 TO: 26-07-29 23:59 EST

OBBB - BAHRAIN

E) ALL OPERATORS OF AIRBUS A319/A320/A321 AIRPLANES INTENDING FLYING
INTO/FROM OR OVERFLYING BAHRAIN FIR MUST COMPLY WITH EASA EMERGENCY
AIRWORTHINESS DIRECTIVE 2025-0268-E ISSUED 28 NOV 2025. OPERATORS
MUST ENSURE FULL COMPLIANCE PRIOR TO ENTRY INTO BAHRAIN FIR. FOR MORE
INFO CONTACT AIRWORTHINESS DEPARTMENT, AEROLICENSING (A) MTT.GOV.BH

WARN

OBBB A0056/26 REPLACED BY OBBB A0192/26

FROM: 26-05-25 06:56 TO: 26-08-25 23:59 EST

OBBB - BAHRAIN

D) DAILY BTN 0630-0845

E)

GUN FIRING WILL TAKE PLACE WI THE FLW COORDINATES:

275000N 0493600E

272600N 0495100E

272700N 0502700E

273700N 0502200E

275100N 0495200E

THE ABOVE RECEIVED FROM JEDDAH

F) SFC

G) 5000FT AMSL

OBBB A0055/26 REPLACED BY OBBB A0191/26

FROM: 26-05-25 06:54 TO: 26-08-25 23:59 EST

OBBB - BAHRAIN

D) DLY BTN 0900-1100

Summary

E)

MIL EXERCISE WILL TAKE PLACE WI THE FLW COORDS:

270000N 0502500E
281700N 0491000E
282300N 0492400E
272500N 0503300E

THE ABOVE RECEIVED FROM JEDDAH.

F) 5000FT AMSL

G) 10000FT AMSL

---END OF DOCUMENT---